



MERLETT



ACCESORIOS



RACOR RÓTULA 928502

Hierro cincado=HC

Acero inoxidable AISI-304=SS



RACOR RÓTULA HEMBRA MANGUERA

Referencia	101	102	103	104	105	106	107	108
Figura	A	B	C	C	D	E	F	G
Ø Manguera	50	60	75	80	100	125	150	200



RACOR RÓTULA HEMBRA ROSCA MACHO

Referencia	109	110	111	112	113	114	115	116
Figura	A	B	C	C	D	E	F	G
Ø Rosca	2"	2"	2.1/2"	3"	4"	5"	6"	8"



RACOR RÓTULA HEMBRA ROSCA HEMBRA

Referencia	117	118	119	120	121	122	123	124
Figura	A	B	C	C	D	E	F	G
Ø Rosca	2"	2"	2.1/2"	3"	4"	5"	6"	8"



RACOR RÓTULA MACHO MANGUERA

Referencia	125	126	127	128	129	130	131	132
Figura	A	B	C	C	D	E	F	G
Ø Manguera	50	60	75	80	100	125	150	200



RACOR RÓTULA MACHO ROSCA MACHO

Referencia	133	134	135	136	137	138	139	140
Figura	A	B	C	C	D	E	F	G
Ø Rosca	2"	2"	2.1/2"	3"	4"	5"	6"	8"



RACOR RÓTULA MACHO ROSCA HEMBRA

Referencia	141	142	143	144	145	146	147	148
Figura	A	B	C	C	D	E	F	G
Ø Rosca	2"	2"	2.1/2"	3"	4"	5"	6"	8"



JUNTA RÓTULA NBR NEGRO

Referencia	149	150	151	152	153	154	155	
Figura	A	B	C	D	E	F	G	
Ø Interior mm.	62	84	101	118	140	170	237	

RACOR BAUER 928501

Hierro cincado=HC

Acero inoxidable AISI-304=SS



RACOR BAUER HEMBRA MANGUERA

Referencia	160	161	162	163	164	165	166	
Figura	50	76	89	108	133	159	194	
Ø Manguera	50	75	80	100	125	150	200	



RACOR BAUER HEMBRA ROSCA MACHO

Referencia	167	168	169	170	171	172	173	
Figura	50	76	89	108	133	159	194	
Ø Rosca	2"	2.1/2"	3"	4"	5"	6"	8"	



RACOR BAUER MACHO MANGUERA

Referencia	174	175	176	177	178	178	180	
Figura	50	76	89	108	133	159	194	
Ø Manguera	50	75	80	100	125	150	200	




RACOR BAUER MACHO ROSCA MACHO

Referencia	181	182	183	184	185	186	187	
Figura	50	76	89	108	133	159	194	
Ø Rosca	2"	2.1/2"	3"	4"	5"	6"	8"	



JUNTA BAUER NBR NEGRO

Referencia	188	189	190	191	192	193	194	
Figura	50	76	89	108	133	159	194	
Ø Interior mm.	62	88	105	130	140	165	220	





ABRAZADERA SIN FIN ANCHO 9 mm. W2 928093



CINTA, INOXIDABLE AISI-430, TORNILLO Y GABIA ACERO ZINCADO

Ø Mínimo	8	10	12	16	20	25	32	40	50	60	70	80	90				
Ø Máximo	12	16	20	25	32	40	50	60	70	80	90	100	110				
Unid. Caja	50	50	50	50	50	50	50	50	50	50	50	10	10				
Ø Mínimo	100	110	120	130	140	150	160	170	180	190	200	210					
Ø Máximo	120	130	140	150	160	170	180	190	200	210	220	230					
Unid. Caja	10	10	10	10	10	10	10	10	10	10	10	10					

ABRAZADERA SIN FIN ANCHO 12 mm. W2 928094



CINTA INOXIDABLE AISI-430, TORNILLO Y GABIA ACERO ZINCADO

Ø Mínimo	16	20	25	32	40	50	60	70	80	90	100						
Ø Máximo	25	32	40	50	60	70	80	90	100	110	120						
Unid. Caja	50	50	50	50	50	50	50	50	10	10	10						
Ø Mínimo	110	120	130	140	150	160	170	180	190	200	210						
Ø Máximo	130	140	150	160	170	180	190	200	210	220	230						
Unid. Caja	10	10	10	10	10	10	10	10	10	10	10						

ABRAZADERA SIN FIN ANCHO 9 mm. W4 928095



CINTA, BARRILETE Y TORNILLO ACERO INOXIDABLE AISI-304

Ø Mínimo	8	10	12	16	20	25	32	40	50	60	70	80	90				
Ø Máximo	12	16	20	25	32	40	50	60	70	80	90	100	110				
Unid. Caja	50	50	50	50	50	50	50	50	50	50	50	10	10				
Ø Mínimo	100	110	120	130	140	150	160	170	180	190	200	210					
Ø Máximo	120	130	140	150	160	170	180	190	200	210	220	230					
Unid. Caja	10	10	10	10	10	10	10	10	10	10	10	10					

ABRAZADERA SIN FIN ANCHO 12 mm. W4 928096



CINTA, BARRILETE Y TORNILLO ACERO INOXIDABLE AISI-304

Ø Mínimo	16	20	25	32	40	50	60	70	80	90	100						
Ø Máximo	25	32	40	50	60	70	80	90	100	110	120						
Unid. Caja	50	50	50	50	50	10	10	10	10	10	10						
Ø Mínimo	110	120	130	140	150	160	170	180	190	200	210						
Ø Máximo	130	140	150	160	170	180	190	200	210	220	230						
Unid. Caja	10	10	10	10	10	10	10	10	10	10	10						

